

Product Change Notice

QD4-099 Rev.A0

Product(s) Affected:

BOXER-6641-A1-1010
BOXER-6641-A2-1010
BOXER-6641-A4-1010
BOXER-6641-A5-1010
BOXER-6641-A6-1010

Date Effective: 2021.11.12

Due to the product strategy and improvement, we decide to adopt a revision motherbaord to replace the original one for the BOXER-6641 series. This replacement passes functions test without effect system performance or drivers change and will bring the system higher stability and reliability.

For the new part number, please refer to below comparison table, please be kindly noted and thanks for your attention and understanding.

Date of Publication: 2021/09/17

-Update the new part number version from 1011 to 1110

Changes to Product:

Purpose of Change:

We always devote to improve our products to bring customer better experience, therefore, we move our BOXER-6641 series product to next version to bring customer a better experience and stability and all the specifications keep the same as previous version.

For the new part number, please refer to below comparison table, please be kindly noted and thanks for your attention and understanding.

☐ Benefits ☒ Impacts:

Model:

BOXER-6641-A1-1010
 BOXER-6641-A2-1010
 BOXER-6641-A4-1010
 BOXER-6641-A5-1010
 BOXER-6641-A6-1010

Driver:

Keep the same

BIOS:

Change

OS Support:

Keep the same

Pre-Change		Post-Change	
BOXER-6641-A1-1010		BOXER-6641-A1-1110	
BOXER-6641-A2-1010		BOXER-6641-A2-1110	
BOXER-6641-A4-1010		BOXER-6641-A4-1110	
BOXER-6641-A5-1010		BOXER-6641-A5-1110	
BOXER-6641-A6-1010		BOXER-6641-A6-1110	
Issue Date	2021.09,17	Issue by	Raven Hsu