

Product Change Notification

| Issue Date | Notification No. | Implementation Date |
|------------|------------------|---------------------|
| 2021/05/10 | X | |

This is to advise you the following products information

Product Identification:

| | | | |
|----------------------|--------------------|--------------------|----------------------|
| AM800480BTMQWA0H | AM800480BTMQWTA0H | AM800480B2TMQWTA0H | AM800480B3TMQWT11H |
| AM800480B3TMQWTA0H-A | AM800480B3TMQWTA8H | AM800480BTMQWA6H | AM800480B3TMQWTO4H-A |
| AM800480BTMQWTGOH-B | AM800480BTMQWTACH | | |

Description of change:

Please kindly be informed that the original LED Driver G5968C is EOL. Ampire will change LED driver from G5968C to TPS61185.



The PCB version change from 800480B-A0H REV.A to 800480B-A0H REV.B

There is no any change on the LCD dimension, and interface.



They are compatible of the electronic,mechanical ,Optical and reliability feature.

Last time buy date : 2021.05.30

Current(G5968C) (PCB Version: 800480B-A0H REV.A)



New(TPS61185) (PCB Version: 800480B-A0H REV.B)



Suggested Alternate Parts and/or Manufacturers:

In case of further questions, please contact your contact. If you do not ask a new sample for approval, Ampire confirms that you approve the Ampire replaced parts of above items. All the replaced parts are approved by Ampire thus if you need a new sample for approval, please ask your contact.